

CombiMill Gearbox

	J	K	L	M	N	O
1						
2						
3			Ratio HighSpeed	Ratio LoSpeed		
4						
5	0x70		1.00		1.00	
6	112					
7	0x50		1.25		1.25	
8	80					
9	0x68		1.66		1.66	
10	104					
11	0x48		2.10		2.10	
12	72					
13	0x10			1.00	2.50	
14	16					
15	0x28			1.33	3.33	
16	40					
17	0x08			1.68	4.20	
18	8					
19	0x24			2.22	5.55	
20	36					
21	0x04			2.77	6.94	
22	4					
23	0x22			3.7	9.26	
24	34					
25	0x02			4.65	11.62	
26	2					
27	0x21			6.25	15.62	
28	33					
29	0x01			8.00	20.00	
30	1					
31						
32						
33						