



Probe A to RxA to Data-

Probe B to RxB to Data+

Scope set to A-B

Probe GNds not connected

500 micro sec division

2vdc

Linxcnc OFF



Linxcnc ON

Filter tree

- Components
 - Pins
 - axis
 - axisui
 - halui
 - hm2_7i92
 - 0
 - debug
 - 7i70
 - dpll
 - gpio
 - led
 - packet-error
 - packet-error-exceeded
 - packet-error-level
 - read-request
 - read
 - sserial
 - ssi
 - 00
 - data-invalid
 - xpositol
 - count
 - index-enable
 - position
 - rawcounts
 - reset
 - watchdog
 - write
 - ini
 - iocontrol
 - joint
 - motion-command-handler
 - motion-controller
 - motion
 - pid
 - servo-thread
 - spindle
 - Parameters
 - Signals
 - Functions
 - Threads

SHOW WATCH SETTINGS

59095685	hm2_7i92.0.ssi.00.xpositol.rawcounts
59095680.0	hm2_7i92.0.ssi.00.xpositol.position
59095685	hm2_7i92.0.ssi.00.xpositol.count