


Friendess BCS100 FSCUT Controller Precitec Raycus WSX Laser Head Preamplifier BCL-AMP Sensor Amplifier

Pinout testing with Multimeter.

Pin 1 = 0 ohms to the body, closed circuit.



Pin 2 = open circuit / no continuity.



Pin 3 = 0 ohms, closed circuit.



Pin 4 = 0 ohms, closed circuit.

