


Cut Recovery



This is a dialog which allows the torch to move away from the cut to find a good piece of material to restart the cut from. This function is only available from the Extras panel and is only valid while paused.

If you need to follow the cut path then use the [paused motion](#) controls at the top of the dialog. When satisfied with the position you can move off the cut path by pressing the direction buttons. Each press of a direction button will move the torch a distance equivalent to the kerf width of the currently displayed material.

Once the torch has been moved off the cut path then the paused motion controls will be disabled.

Pressing Cancel (or the X at the top left) will cause the torch to move back to where it was prior to using the direction buttons and the dialog will close.

Once you are happy with the torch position you can press Resume Cut or the Resume button on the GUI and the cut will resume from the current position. The dialog will close when the torch returns to where it was prior to using the direction buttons.